

### **TPM300E/TPM350 Charging Procedure**

To charge the battery powered transporters, you must first disconnect the clip in power supply from the battery to the power point on the machine – shown below.



With these disconnected, the lower point, coming from the battery pack, connects straight to the battery charger.

